

POPPLETON HISTORIC STUDY

B.2502

MAG1#0425025404

<u>Block</u>	<u>Lot</u>	<u>Address</u>
185	103-96	1015-1029 W. Lexington Street

Approximate age

1800-1845

1845-1860

1865-1880

1880-1896

1896-on

(c. 1842-1845)

<u>Rating</u>	<u>Architectural</u>	<u>Condition</u>
A	Significant-save	good fair poor bad
B	Quality-Indiv./groups-save	good fair poor bad
C	Important to street/groups	good fair poor bad
D	Insignificant/detrimental	good fair poor bad

Notable features:

This group is about a decade older than the houses west of them. They are 2½ story, some are at street level or only a step above. They appear on the 1851 maps as part of a group which connected with a north-south lane running between Lexington and Fayette Streets at this point. Number 1029 has an original doorway applied at the time the windows were replaced with arched openings (1870's?). Number 1015 has been formstoned; 1023 has been stuccoed. Number 1021 had a storefront.



The entire group should be rehabilitated as small dwellings.

Environmental context:

Vacancy rate is high: 1027, 1025, 1021. Others are in poor condition. (See comment for 1031-1047 W. Lexington Street.)



Baltimore 1890 vol. 3, Sheet 85_b



B-2502
1015-1029 W. Lexington Street (1019 & 1021 demolished)
Block 0185, Lots 096-103
Baltimore City
Baltimore West Quad

